


20 025 000 HOSPITA PILLAR TAP



SPARE PARTS, March 2013 – now

- 1: Lever (Spare part-nr. 45316000)
- 1.1: Replacement handle connection kit (Spare part-nr. 45620000)
- 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
- 2.1: O-Ring Ø18,2 x Ø1,7 (Spare part-nr. 0392400M)
- 3: Shank fastening assembly (Spare part-nr. 45000000)
- 4: Flow restrictor (Spare part-nr. 13929000)
- 5: Strainer jet regulator
- Sistra M24x1 (Spare part-nr. 13905000)

20 025 000 HOSPITA PILLAR TAP

No exploded view is available for this spare part list.

SPARE PARTS, January 1993 – March 2013

- 1: Lever (Spare part-nr. 45316000)
- 1.1: Replacement handle connection kit (Spare part-nr. 45620000)
- 2: Ceramic headpart, 1/2" (Spare part-nr. 45882000)
- 2.1: O-Ring Ø18,2 x Ø1,7 (Spare part-nr. 0392400M)
- 3: Shank mounting kit (Spare part-nr. 45004000)
- 4: Flow restrictor (Spare part-nr. 13929000)
- 4.1: Repl.kit f.aerator M22x1 and M24x1 (Spare part-nr. 45002000)
- 5: Strainer jet regulator
- Sistra M24x1 (Spare part-nr. 13905000)
- 5.1: Strainer (Spare part-nr. 45797000)