

## 20 893 000 SENTOSA THREE-HOLE BASIN MIXER 1/2"

### SPARE PARTS, January 1994 – now

- 1: Handle 1/2" (Sentosa) (Spare part-nr. 45538IP0)
  - 1.1: Replacement handle connection kit (Spare part-nr. 45186000)
    - 1.1.1: O-Ring Ø18,2 x Ø1,7 (Spare part-nr. 0392400M)
  - 1.2: Guide ring (Spare part-nr. 0202100M)
- 2: Sentosa handle, hot (Spare part-nr. 45539IP0)
  - 2.1: Replacement handle connection kit (Spare part-nr. 45186000)
  - 2.2: Guide ring (Spare part-nr. 0202100M)
- 3: Ceramic headpart, 1/2" (Spare part-nr. 45346000)
  - 3.1: O-Ring Ø18,2 x Ø1,7 (Spare part-nr. 0392400M)
- 4: Escutcheon (Spare part-nr. 04698000)
- 5: Shank fastening assembly (Spare part-nr. 45025000)
- 6: Coupling nut 1/2" x 10.5 mm (Spare part-nr. 1290100M)
  - 6.1: Fibre seal dia. Ø 18,5 x Ø 12 x 2 (Spare part-nr. 0138900M)
- 7: Escutcheon (Spare part-nr. 04696000)
- 8: Shank mounting kit (Spare part-nr. 45226000)
- 9: Flow restrictor (Spare part-nr. 13929000)
  - 9.1: Repl.kit f.aerator M22x1 and M24x1 (Spare part-nr. 45002000)
- 10: Flexible hose (Spare part-nr. 45461000)
- 11: Pop-up rod (Spare part-nr. 07511000)
- 12: Pop-up waste set 1 1/4" (Spare part-nr. 28910000)
  - 12.1: Chrome bath plug (Spare part-nr. 07182000)
  - 12.2: Eccentric rod (Spare part-nr. 07052000)

No exploded view is available for this spare part list.