


## 43 907 PI0 REPLACE KIT SET



### SPARE PARTS, November 2013 – now

- 1: Filling valve (Spare part-nr. 37095000)
- 1.1: Lever (Spare part-nr. 43734000)
- 1.1.1: Sealing washer (Spare part-nr. 4377000M)
- 1.2: Valve head (Spare part-nr. 43536000)
- 1.3: Membrane (Spare part-nr. 4375800M)
- 1.4: Screw cap (Spare part-nr. 43735000)
- 1.5: Valve FLOAT, 5 pcs.. (Spare part-nr. 4379100M)
- 1.6: Set of seals (Spare part-nr. 43722000)\*
- 2: Push button and escutcheon (Spare part-nr. 37117PI0)
- 3: Push bar 350 mm (Spare part-nr. 43535000)
- 4: Pop-up rod (Spare part-nr. 43540000)
- 5: Servo discharge valve (Spare part-nr. 43486000)
- 5.1: Outlet piston (Spare part-nr. 43544000)
- 5.1.1: Sealing washer (Spare part-nr. 43808000)
- 6: Seat (Spare part-nr. 43533000)
- 7: Sealing washer (Spare part-nr. 43745000)
- 8: Fixing set (Spare part-nr. 43500000)
- 9: Push button and escutcheon (Spare part-nr. 37115PI0)\*
- 10: Push rod (Spare part-nr. 38005000)\*
- 11: SPECIAL adapter set (Spare part-nr. 37123000)\*
- 12: Valve seat (Spare part-nr. 42153000)\*

\* Optional accessories