


25 135 000 GET TWO-HANDLED BATH FILLER 1/2"



SPARE PARTS, November 2010 – now

- 1: Handle Get red (Spare part-nr. 48085000)
- 1.1: Replacement handle connection kit (Spare part-nr. 45186000)
- 1.1.1: O-Ring Ø18,2 x Ø1,7 (Spare part-nr. 0392400M)
- 2: Handle Get blue (Spare part-nr. 48086000)
- 2.1: Replacement handle connection kit (Spare part-nr. 45186000)
- 3: Ceramic headpart 3/4", 180° (Spare part-nr. 45887000)
- 4: Ceramic headpart 3/4", 180° (Spare part-nr. 45888000)
- 5: Repl.kit f.rotary valve (Spare part-nr. 48038000)
- 6: Flow straightener (Spare part-nr. 46164000)
- 7: Non-return valve (Spare part-nr. 08565000)
- 8: Repl.kit f.shank fastening 3/4" (Spare part-nr. 45163000)